

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

KACHESS DAM, DIKE CLOSING 1913 SPILLWAY

HAER WA-79-C

Kachess River, 1.5 miles north of Interstate 90

Easton vicinity

Kittitas County

Washington

J. Thomas Wilson, Photographer, September-October 1992 (HAER WA-79-C-7 and 2)

INDEX TO BLACK AND WHITE PHOTOGRAPHS

WA-79-C-1	UPSTREAM FACE OF DIKE CLOSING ORIGINAL 1913 SPILLWAY, LOOKING SOUTHEAST
WA-79-C-2	DOWNSTREAM FACE OF DIKE CLOSING 1913 SPILLWAY, LOOKING WEST
WA-79-C-3	Photographic copy of photograph, photographer unknown, 30 September 1911 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "DRY PAVING BELOW WEIR IN SPILLWAY CHANNEL"
WA-79-C-4	Photographic copy of photograph, photographer unknown, 1 August 1912 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "VIEW OF TRESTLE AND CONCRETE PLANT AT SPILLWAY, PART OF WEIR FORMS WITH BULKHEADS, AND DRY PAVING ABOVE THE WEIR IN FOREGROUND TO THE RIGHT"
WA-79-C-5	Photographic copy of photograph, photographer unknown, 1911 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "CONCRETE PLANT AT SPILLWAY"

KACHESS DAM, DIKE CLOSING 1913 SPILLWAY

HAER WA-79-C

INDEX TO PHOTOGRAPHS

(Page 2)

- | | |
|-----------|---|
| WA-79-C-6 | Photographic copy of photograph, photographer unknown, September 1912 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "SPILLWAY LOOKING SOUTH" |
| WA-79-C-7 | Photographic copy of photograph, G.G. Rollstin, photographer, 19 June 1936 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "KACHESS DAM SPILLWAY. VIEW OF OLD SPILLWAY WEIR" |
| WA-79-C-8 | Photographic copy of photograph, G.G. Rollstin, photographer, 24 June 1936 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "BREAKING CONCRETE IN OLD SPILLWAY FLOOR [IN PREPARATION FOR PLUGGING THE SPILLWAY WITH THE DIKE]" |
| WA-79-C-9 | Photographic copy of photograph, G.G. Rollstin, photographer, 27 July 1936 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office Yakima, Washington). "SHOWING EXCAVATION OF CONCRETE AND RUBBLE PAVING IN OLD SPILLWAY CHANNEL, LOOKING WEST" |